Appendix

Risk Table (from original Project Plan)

Risk	Level (high/Medium/Low)	High level management strategy
Failure to recruit research staff	Low	Suitable staff have been identified. The Centre for Environmental Economics and Policy (UWA) is well connected and can bring other skills to support staff if needed.
Research staff leave the project	Low	Reallocation of workloads to other suitable project members.
Mismatch between economic and simulation data	Medium	Inception meeting to define project scope and assets. Regular meetings with UWA and UOM to ensure alignment of approaches.
Limited access to in-kind resources via Project Scoping Team	Low	CRC will work closely with the industry representatives to retain interest in the project and will seek advice from API and ENA as required.
Limited access to industry data	Medium	Develop a plan with all project stakeholders on suitable alternate sources of data to be used and circulate agreed data access.
Communication failure between UoM and UWA	Low	Establish a communication strategy in consultation with the BNHCRC and agree on a set of project communication tasks.
Failure to deliver project to budget	Medium	Clearly identify out of scope items and present them at initial scoping workshop. Flexibility to reallocate resources and prioritise outcomes based on the Project Scoping Team advise and direction
Failure to deliver project to schedule	Medium	Communicate from the start of the project data needs and clear task descriptions for obtaining data in the format required